

UNFPA Prequalified Male Condom Factories (in alphabetical order)

Dated: 31 January 2011



Factory	Country	Prequalified Manufacturing site*	Most recent year of Prequalification**	Re-inspection Status
Beiersdorf Medical Latex (DUA)	Malaysia	<p><u>Address:</u> Plo 8, Senai Industrial Estate, Johor, 81400 Sennai</p> <p><u>Telephone:</u> 00 60 7-597 8100 <u>Fax:</u>00 60 7-599 1316</p> <p><u>Website:</u> www.beiersdorf.com</p>	2006	Re-inspected in 2010, submitting corrective reports
CPR Produktions Und Vertriebs GmbH	Germany	<p><u>Address:</u> Im Kirchenfelde 8, 31157 Sarstedt</p> <p><u>Telephone:</u> 00 49 50 66/9 94-51 <u>Fax:</u> 00 49 50 66/51 18</p> <p><u>Website:</u> www.cpr-germany.com</p>	2009	
CUPID Limited	India	<p><u>Address:</u> A - 68, M.I.D.C. (Malegaon), Sinnar, 422113 Nashik</p> <p><u>Telephone:</u> 00 91 2551-230772/230280 <u>Fax:</u> 00 91 2551-230279</p> <p><u>Website:</u> www.cupidcondom.com</p>	2008	
Dongkuk Vietnam	Vietnam	<p><u>Address:</u> No. 10 - Thuy Van Industrial Zone, Phu Tho Province, Viet Tri City</p> <p><u>Telephone:</u> 00 84 210-953 901/2 <u>Fax:</u> 00 84 210-857 365</p> <p><u>Website:</u></p>	2010	
Guangzhou Double-One Latex	China	<p><u>Address:</u> 9 Jinsha Road, Gongye Avenue</p> <p><u>Telephone:</u>00 86 20 - 84348008 <u>Fax:</u> 00 86 20 - 84364642</p> <p><u>Website:</u> www.gzrubber.com</p>	2009	
Guilin Latex	China	<p><u>Address:</u> No. 6 Wushan Road, Guilin 541001, P.R. China</p> <p><u>Telephone:</u> +86 773 255 0144 <u>Fax:</u> +86 773 255 9998</p> <p><u>Website:</u> www.g121.cn</p>	2009	
HLL Lifecare Limited - Kakkanad	India	<p><u>Address:</u> Plot N^o 16-A/1, Cochin Special Economic Zone, Kakkanad 6800387</p> <p><u>Telephone:</u> +91 484 241 3332 <u>Fax:</u> +91 484 241 3293</p>	2009	

*Manufacturers have many manufacturing sites. This Prequalified list is specific to the specific manufacturing site listed.

**Prequalified manufacturers are re-inspected every 3 years in order to maintain their prequalification status.

UNFPA Prequalified Male Condom Factories (in alphabetical order)

Dated: 31 January 2011



Factory	Country	Prequalified Manufacturing site*	Most recent year of Prequalification**	Re-inspection Status
HLL Lifecare Limited - Peroorkada	India	<u>Address:</u> Post Box. No. 2, Peroorkada Factory, Thiruvananthapuram 695 055, Kerala <u>Telephone:</u> +91 471 2437270, 2433459, 2436227 Fax: +91 471 2432409, 2430572	2007	Re-inspected in 2010, submitting corrective reports
Innolatex	Malaysia	<u>Address:</u> Lot 594, Persiaran Raja Lumu, Pandamaran Industrial Estate, 42000 Port Klang, Selangor Darul Ehsan. <u>Telephone:</u> +603 3168 1613/0702 Fax: +603 3167 8070	2007	Re-inspected in 2010, submitting corrective reports
Indus Medicare	India	<u>Address:</u> NH-7, Survey No. 129, Ramaipally (V), Toopran (M), Medak District, Andhra Pradesh, 502 334 <u>Telephone:</u> +91 8454 235451	2007	Re-inspected in 2010, submitting corrective reports
Karex	Malaysia	<u>Address:</u> Lot 2244, BT.391/2, 82000 Pontian Besar, Johor <u>Telephone:</u> +6 07 6881996, +6 07 6881050 Fax: +6 07 6882755	2007	Re-inspected in 2010, submitting corrective reports
Mercator Healthcare Ltd	India	<u>Address:</u> 3rd Km. Budhana Rd, Muzaffar Nagar - 251002, (U.P.) <u>Telephone:</u> +91 131 245 1553 Fax: +91 131 245 1554	2009	
Nulatex Sdn Bhd	Malaysia	<u>Address:</u> Lot 1870, 4th Miles, Jalan mengkibol 8600, Kluand, Johor, Malaysia <u>Telephone:</u> +607 777 1801 Fax: + 607 777 1805	2009	

*Manufacturers have many manufacturing sites. This Prequalified list is specific to the specific manufacturing site listed.

**Prequalified manufacturers are re-inspected every 3 years in order to maintain their prequalification status.

UNFPA Prequalified Male Condom Factories (in alphabetical order)

Dated: 31 January 2011



Factory	Country	Prequalified Manufacturing site*	Most recent year of Prequalification**	Re-inspection Status
Polar Pharma Ltd	India	<u>Address:</u> Plot No. 3, Somnathpur Industrial Estate, Remuna, Orissa, 756 019, Balasore/Orissa <u>Telephone:</u> <u>Website:</u> www.polarpharma.com	2008	
Qingdao Double Butterfly Group	China	<u>Address:</u> 103 Taidong 1st Rd, Qingdao <u>Telephone:</u> +86 532 361 3131 Fax: +86 532 362 1809 <u>Website:</u> www.qdbg.com	2008	
Suretex Ansell	Thailand	<u>Address:</u> 31/1 Moo 4, Tambon Khao Hua Kwan, Amphur Phunphin, 84130, Surati Thani <u>Telephone:</u> 00 66 77 240941 6 <u>Website:</u> www.ansell.com	2009	
Suretex Prophylactics Ltd	India	<u>Address:</u> Plot No. 74 to 91, Kiadb Industrial estate, Jigani II phase, Anekal Taluk, 562 106, Bangalore <u>Telephone:</u> 00 91 80-7826217 Fax: 00 91 80-7826219	2009	
Suzhou Colour-way Enterprise Development Co. Ltd	China	<u>Address:</u> Jiangyin Colour-way, Haushi Industry Park, Jiangyin <u>Telephone:</u> +86 512 653 71793, 512 653 71065 Fax: 512 653 79978 <u>Website:</u> www.colour-way.com	2010	
Thai Nippon	Thailand	<u>Address:</u> Laem Chabang Indus. Estate, 49-49/1 EPZ 1, Thungsukla, Sriracha, 20230, Chonburi <u>Telephone:</u> 00 66 38-490258 Fax: 00 66 38-390414	2009	

*Manufacturers have many manufacturing sites. This Prequalified list is specific to the specific manufacturing site listed.

**Prequalified manufacturers are re-inspected every 3 years in order to maintain their prequalification status.

UNFPA Prequalified Male Condom Factories (in alphabetical order)

Dated: 31 January 2011



Factory	Country	Prequalified Manufacturing site*	Most recent year of Prequalification**	Re-inspection Status
Tianjin Human Care Latex Corporation	China	<u>Address:</u> No. 223 West 14 Road Tianjin, Airport Industrial Park Tianjin 300308 <u>Telephone:</u> +86 22 604 57783 Fax:+86 22 604 57586	2008	
TTKLIG Pallavaram	India	<u>Address:</u> No. 35, Old Trunk Road, Pallavaram, Chennai 600 043 <u>Telephone:</u> 044 42206100 Fax: 914422640032 <u>Website:</u> www.ssl-international.com	2007	Re-inspected in 2010, submitting corrective reports
TTKLIG Pudhucherry	India	<u>Address:</u> No. 12, Kothapuri Natham Road, Thiruvandar Koil, Mannadipet Commune, Pudhucherry 605 102 <u>Telephone:</u> 0413 264 1926, 2641927 Fax: 0413 2641109 <u>Website:</u> www.ssl-international.com	2007	Re-inspected in 2010, submitting corrective reports
TTKLIG Virudhunagar	India	<u>Address:</u> 20 Perali Road, Virudhunagar <u>Telephone:</u> 00914562245348 -350 Fax: 00914562245302 <u>Website:</u> www.ssl-international.com	2007	Re-inspected in 2010, submitting corrective reports
UNIDUS China	China	<u>Address:</u> Xizhang Town, Zhangjiangang City, Jiangsu <u>Telephone:</u> +86 512 5845 2628 Fax: +86 512 5845 2638 <u>Website:</u> www.uniduschina.com	2007	Re-inspected in 2010, submitting corrective reports
UNIDUS Korea	Korea	<u>Address:</u> 106-1, Yonggang-ri, Jeungpyoung-Eup, Jeungpyoung-Gun, Choongchengbuk-Do <u>Telephone:</u> +82 43 836 0025 Fax: +82 43 836 5254 <u>Website:</u> www.unidusok.com	2007	Re-inspected in 2010, submitting corrective reports

*Manufacturers have many manufacturing sites. This Prequalified list is specific to the specific manufacturing site listed.

**Prequalified manufacturers are re-inspected every 3 years in order to maintain their prequalification status.